

This report has been specifically carried out for a participant of the RACQ Approved Dealer Network
Phone 13 1905 to book a full RACQ Mastercheck

Customer: CAMCRAFT PTY LTD T/A CAR XPRESS
Address: 1387 GYMPIE RD

Make and Model: TOYOTA LANDCRUISER GXL (4x4)
Registration: 542JKR
Build Date: 9 / 2004
Expires: 04/2010
ADR Date: 9 / 2004
Odometer: 215,900
Body Type: WAGON
VIN: JTEHTO9J405508685
Road Test Speed: 60km/h
Weather: Fine

Membership No:
Inspection Date: 3-Aug-2009

Interior

- 1 Doors, Locks
- 2 Glass, Mirrors
- 3 Seats, Seat Belts
- 4 Interior Condition

Electrical

- 5 Interior/Exterior Lights
- 6 Battery
- 7 Wipers, Washers
- 8 Horn
- 9 Heater, Demister system
- 10 Air Conditioning
- 11 Dash Warning Lights/Gauges

Road test

- 12 Ease of Starting
- 13 Engine Performance
- 14 Drive Train Operation
- 15 Steering and Suspension
- 16 Speedometer, Odometer (visual)
- 17 Brake Operation


Underbody

- 18 Panels
- 19 Frame and Members
- 20 Exhaust System
- 21 Front Suspension
- 22 Rear Suspension
- 23 Shock Absorbers
- 24 Steering Components
- 25 Drivetrain
- 26 Axle Bearings
- 27 Drive Shafts, Universals, CV Joints
- 28 Clutch Controls
- 29 Brake Master Cylinder, Pipes & Fittings

Engine

- 30 Power Balance
- 31 Engine Noises
- 32 Engine Fumes, Exhaust Smoke
- 33 Oil Level, Condition, Seals
- 34 Mountings
- 35 Visual Emission Components
- 36 Cooling System, Water Hoses
- 37 Auxiliary Drive Belts
- 38 Fuel System
- 39 Ignition System

Tyres and Wheels



Defect Present - Attention Required

Worn

44 Tread Tyre

Other Items Noted

- 2 Front Windscreen
 - 2 Rear Tinting
 - 4 Left Hand Sunvisor
 - 4 Various Upholstery / Trim
 - 5 Centre Interior Light/s
 - 9 Centre Heater / Airconditioning Vents
- Front windscreen chipped
Tinting scratched
Sunvisor mount loose
General wear and tear to trims
Interior light inoperative
Vent air direction control inoperative

Inspectors Comments

Drink holder trim missing at rear of concole.; This vehicle is considered to be generally in a good condition